ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0298, W0527, W0304	Manjunath Floor Mill Rd, NA	Chairman Veeranna Layout
Segment No.	**Total Length (m)**	
6/C-W0298/S125851	261.33	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	131.23	77.608147	13.060873	77.609356	13.060820	W0527	M0013
2	130.10	77.608109	13.061131	77.609308	13.061099	W0527	M0013

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at Chairman Veeranna Layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	4900000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvement to Roads and Drains at Chairman Veeranna Layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-15-000028
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/19/2016-17	30/04/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/04/2016	29/04/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
V. CHANDRAPPA		0.00
Phone No.	**E-Mail ID**	
9448447181		

Field Inspection Details

Number of Trees	Any Other Information	Name
3		KRISHNAPPA
Date of Inspection	**Remarks**	
27/11/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0298, W0527, W0304

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/11/2016	27/12/2016	COMPLETED
SE	VASU K M	27/11/2016	27/12/2016	COMPLETED
EE	YARAPPA REDDY	27/11/2016	27/12/2016	COMPLETED
AEE	J N LOKESH	27/11/2016	27/12/2016	COMPLETED
AE	KRISHNAPPA	27/11/2016	27/12/2016	COMPLETED
AE	KRISHNAPPA	27/11/2016	27/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0298, W0527, W0304